

MatrixCAE - version 4.3 – SP6 - Release note

Processed in version 4.3 SP6 (July 2011):

MatrixFrame® Toolbox:

- I. Concrete code check
 - a. In module Column + Fire was the check for 2nd order with use of table 28 and 29 done according NEN6720 7.6.2 instead of 7.7.2.1. This has been resolved.

MatrixFrame® General:

- I. Concrete code check:
 - a. In stirrups calculation in a beam with deep beam parts and normal parts was incidentally the z used from normal parts for a deep beam part. This has been resolved.

2D Frame:

- I. Timber code check:
 - a. The input of buckling length in z was not on influence on the calculations. System length was always used. This has been resolved.

End release note